

0-37-200450- 8

26 September 1967

Page 1 of 3

EVALUATION SUMMARYMission BX-6723

1. Processing and Titling - Performed in the field
2. Physical Condition - Fair (as received)*
3. Hypo Retention - Negligible
4. Exposure (based on density) - Medium to light
5. General Comments:
- A. Cloud Cover - 30%
- *B. Received with intermittent emulsion scratches.

Processing folder -

MISSION NO. BX-6723 EVALUATION REPORT

Evaluated By Q.C. Technicians Camera Fwd/Aft
 Evaluation Date 20 September 1967 Emulsion 3404

Film Metering Normal for system
 Film Tracking Good
 Clock Operation Exposure Good
 Counter Operational
 Data Chamber (image quality) Good
 Apparent Resolution Normal
 Apparent Granularity Normal
 Density Medium to light
 Contrast Medium to low

Discrepancies:

<u>Part</u>	<u>Frames</u>	<u>Comments</u>
Preflight		Kinks, embedded dirt, fog
1	1 1-75	Kinks, embedded dirt Emulsion scratches
2	76-150 77,80,83	Intermittent kinks Pinholes
3	154,198,227	Kinks
4	230-234	Base scratch
5	306	Embedded dirt
6	382,456	Embedded dirt
7	451-525 472,474,486, 488 478,486,492	Intermittent emulsion scratch Embedded dirt Kinks
8	533,535,542, 559,560,600 533	Kinks Abrasions

Page 3 of 3

Discrepancies (Cont'd) ^{Fwd/} _{Aft} Camera

<u>Part</u>	<u>Frames</u>	<u>Comments</u>
9	601-675	Intermittent emulsion scratches
10	676-750 720	Intermittent emulsion scratch Comet
11	797,798 751-825	Splice Emulsion scratches
12	826-900 863	Emulsion scratches Comet
13	901-975 935 943,945 956 961,964	Emulsion scratches Abrasion Pinholes Splice Emulsion cracks
14	1001-1016 1015-1022 1015	Abrasions Fog Emulsion scratch
Postflight		Kinks, abrasions, fog